

VEHICLE INSPECTION REPORT

SY14LTA

MAZDA MAZDA 3 D SE-L

Inspection

Vehicle

VAT	Margin
V5	Buyer To Apply

Details

Reg. date	31/03/2014	Colour	SILVER	GVW	1910kg
Year	2014	VIN	JMZBM642611130250	Gearbox	MANUAL
Mileage	114,849 Miles Not Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Diesel	Body / Panel Wrap	No Wrap	Doors	5

SERVICED @ 22K & 35K, 2 KEYS. LOG BOOK TO APPLY FOR

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

