

# VEHICLE INSPECTION REPORT

**DL09LHG**

## VOLKSWAGEN TOURAN S TDI 105

### Inspection

### Vehicle

VAT	Margin
V5	Present

### Details

<b>Reg. date</b>	01/04/2009	<b>Colour</b>	BLACK	<b>Body / Panel Wrap</b>	No Wrap
<b>Year</b>	2009	<b>VIN</b>	WVGZZZ1TZ9W082602	<b>GVW</b>	2210kg
<b>Mileage</b>	112,366 Miles Not Warranted	<b>Body Style</b>	MPV	<b>Gearbox</b>	MANUAL
<b>Fuel Type</b>	Diesel	<b>MOT Due</b>	05/02/2027	<b>Gears</b>	6

### Tyres

NSF
NSR
OSF
OSR
Spare

### Photos

