

VEHICLE INSPECTION REPORT

LD07NFP

KIA SEDONA LS

Inspection

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	23/03/2007	Colour	BLUE	Body / Panel Wrap	No Wrap
Year	2007	VIN	KNEMB754266101978	GVW	2900kg
Mileage	146,035 Miles Not Warranted	Body Style	MPV	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	21/10/2026	Gears	5

Tyres

NSF

NSR

OSF

OSR

Spare

Photos

