

VEHICLE INSPECTION REPORT

MF10FYO

MINI MINI MINI COOPER

Inspection

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	05/03/2010	Body Style	Hatchback	GVW	1515kg
Year	2010	Service history	Full	Gearbox	MANUAL
Mileage	90,250 Miles Not Warranted	Service documents	Service Book	Gears	6
Fuel Type	PETROL	Number of stamps	9	Doors	3
Colour	RED	MOT Due	30/05/2027		
VIN	WMWMF32060TV61619	Body / Panel Wrap	No Wrap		

FULL SERVICE HISTORY LAST DONE IN AUGUST @89K

Tyres

NSF

NSR

OSF

OSR

Spare

Photos

